




Quanser Specialty Experiment Series:

Shake Table II: User Manual

Shake Table II



User Manual

Table of Contents

1. Introduction.....	1
2. System Specifications and Description.....	1
2.1. Shake Table.....	1
2.2. Universal Power Module 50-25-3PHI.....	2
2.3. Data Acquisition System.....	7
2.4. Control Software.....	8
3. Connection Procedure.....	9
3.1. Cable Nomenclature.....	9
3.2. Connecting the Terminal Board.....	11
3.3. Typical Connections.....	12
3.4. Signals in 'Table X' Connection.....	15
4. Running Experiments with WinCon.....	16
4.1. Supplied Simulink Models, WinCon Projects and Software.....	17
4.2. Calibrating Table to 'Home'.....	19
4.3. Sending Sine Wave to Shake Table.....	20
4.4. Variables Available for Plotting.....	21
4.5. Finding Frequency Response of a Structure Floor.....	25
4.6. Performing Analysis on Collected Data.....	26
4.7. Running a Standard Earthquake.....	26
4.8. Scaling a Real Earthquake.....	27
4.9. Compiling a New Earthquake.....	29
5. Troubleshooting Guide.....	31
Appendix A.....	33
A.1. Signals used to Initialize 50-25-3PHI UPM.....	33
A.2. Signals used to Enable 50-25-3PHI UPM.....	33
A.3. Signals used to Calibrate 50-25-3PHI UPM.....	34

1. Introduction

Shake Table II is an instructional shake table developed for the University Consortium on Instructional Shake Tables (UCIST). The system is comprised of a shake table, a universal power module (UPM), a data acquisition card (DAC) along with its external terminal board, and a PC running control software. The PC sends and receives signals through the data acquisition card using WinCon. Consider the signal transitions when sending a sine wave to the shake table and reading its resulting acceleration. The sine wave is generated by the PC using WinCon and is sent through the DAC to the UPM. The signal is then amplified by the power amplifier in the UPM and a voltage is applied to the motor connected to the shake table. The table moves back and forth at the position and frequency of the commanded sine wave. The acceleration of the table is read from the accelerometer sensor attached to the table. The accelerometer is connected to the DAC through the UPM and the acceleration is read using WinCon on the computer. The data can be viewed in real-time and saved for later analysis.

The next section describes the various components of the system and lists their specifications. In Section 3 the typical wiring setup of the shake table is described when using a single x -axis table and when using two shake tables to actuate xy motions. The software programs supplied with the shake table are then explained in Section 4.

2. System Specifications and Description

The specifications and components of the shake table, the UPM, and the DAC will be explained in section 2.1, 2.2, and 2.3, respectively. The computer and the software used to control the shake table are described in Section 2.4. The last section explains the safety features integrated in the UPM device.

2.1. Shake Table

The shake table consists of a 1 Hp brushless servo motor driving a $\frac{1}{2}$ in lead screw. The lead screw circulates through a ball nut that is attached to the 18×18 in² table platform. The table slides on low friction linear ball bearings on two ground hardened shafts. The specifications of Shake Table II are given in Table 1.

<i>Parameter</i>	<i>Value</i>	<i>Units</i>
Table dimensions	18 × 18	in ²
Maximum payload	33	lb
Operational bandwidth	20	Hz
Peak velocity	33	in/s
Ball screw efficiency	90	%
Maximum force	700	N
Peak acceleration	2.5	g
Stroke	± 3	in
Weight	60	lb
Encoder / lead screw resolution	1.25×10^{-4}	in
Motor maximum torque	1.65	N·m
Ball nut dynamic loading capacity	12000	N
Ball nut life expectancy at full load	2.50×10^{10}	in
Linear bearing life expectancy	2.50×10^8	in
Linear bearing load carrying capability	290	lb

Table 1 Shake II Table Specifications

2.2. Universal Power Module 50-25-3PHI

2.2.1 Description

The Shake Table II system is supplied with its custom-designed power amplifier, namely the Universal Power Module model # 50-25-3PHI shown in Figure 1. It consists of a 3-phase PWM brushless amplifier as well as associated electronics for safety operation. It is a current mode amplifier meaning that an input voltage to the amplifier results in a controlled current through the motor. The amplifier current gain, K_a , is given in Table 2: thus applying one Volt at the input will result in K_a Amperes. Note that the maximum voltage that is applied to the motor however is limited by the BUS voltage, V_{bus} , as specified in Table 2.

Apart from powering the Shake Table II DC motor and as all other Quanser's power modules, the UPM 50-25-3PHI also contains an independent power supply, which is used to power instrumentation and/or signal condition of external analog sensors such as

accelerometers, strain gages, potentiometers, or also proximity sensors. Specifically, it is a 1-Ampere, ± 12 -Volt regulated DC power supply. The UPM connectors are also fully compatible with our quick connect system enabling you to switch from one experiment to another quickly and efficiently.



Figure 1 Front Panel of UPM

Furthermore, the UPM system is equipped with an embedded PIC micro-controller circuit. It performs several safety functions that ensures the Shake Table II system does not get damaged. These safety functions include:

1. Processing of the limit sensor signals. End of travel limit sensors (either *Left* or *Right*) disable the amplifier when in the *OK* and *Enable* mode. The only way to reset the amplifier is then to trigger the *Home* proximity sensor by manually moving the table back to its mid-stroke position. The limit sensors attached to the shake table are shown in Figure 2 when the table cover is removed.




Figure 2 Limit Sensors

2. Conversely when the UPM is in calibration mode the amplifier is instead disabled when the table reaches the *Home* sensor. In this mode, the amplifier remains enabled when the *Left* or *Right* sensors are triggered, since it uses those for auto-centering. The calibration procedure is explained further in Section 4.
3. After power up, the amplifier is enabled only if a sequence of pulses originating from the DAC board (through Digital Output #8 and #9) is applied to the micro-controller. Refer to the following UPM Starting Procedure and Initialization Section for more details.



Keep the *Safety Override* switch in the OFF position. Turning it on enables the UPM independently of any safety circuitry. It is intended only if the safety circuitry fails and you still want to perform some experiments. **With *Safety Override* ON, nothing protects the table from damage!**

2.2.2 Specifications

Table 2 lists and characterizes the main specifications associated with the UPM 50-25-3PHI system. Some of these parameters can be used for mathematical modeling of the system.

<i>Symbol</i>	<i>Parameter</i>	<i>Value</i>	<i>Units</i>
K_a	PWM Amplifier Current Gain	5	A/V
V_{bus}	PWM Amplifier Bus Voltage Per Phase	48	V
I_{a_max}	PWM Amplifier Maximum Continuous Line DC Current	10	A
I_{a_peak}	PWM Amplifier Peak Line DC Current	25	A
V_{dc}	DC Output Voltage Supply	± 12	V
I_{dc_max}	DC Output Maximum Current Supply	1	A
V_{in}	UPM AC Input Voltage	120	V

Table 2 Universal Power Module Specifications

2.2.3UPM Deadman Switch

The UPM amplifier can only be enabled if a deadman switch as shown in Figure 3 is properly connected. Further the amplifier can only drive the DC motor when the switch is NOT pressed down. The knob in the E-stop switch can be placed in the upright position by rotating the knob clockwise, as indicated by the arrows on the knob, until it is released upwards. Again, in this mode the amplifier can supply voltage to the motor given that the UPM is initialized and the amplifier is enabled.




Figure 3 Deadman Switch



PRESS DOWN on the RED BUTTON of the deadman switch in case of emergency. If something goes wrong during an experiment, pressing the red button of the deadman switch disables the amplifier and shuts off the DC motor power.

2.2.4 UPM Starting Procedure and Initialization

Before being able to run an experiment, the UPM 50-25-3PHI must be started in the following sequence:

1. Ensure that the *Safety Override* switch, located on the UPM front panel, is OFF.
2. Ensure that the Emergency Stop, shown in Table 3, is properly connected into the side of the UPM, as previously described. Pull up on the red knob until released in the upright position.
3. Ensure that the UPM is plugged into the AC outlet and turn on the main power switch (at the back of the unit). The red LED on the top-left corner should be lit.
4. After power up, the UPM system is still not ready as there is no guarantee that it is connected to a computer. The *Left* and *Right* LEDs, on the UPM front panel, should flash. If the lights are NOT flashing disconnect the "Terminal Board-To-UPM" cable, turn off the power on the UPM, and then turn it back on again. The two LEDs should flash. If so, re-connect the "Terminal Board-To-UPM" cable and proceed to Step 5.
5. Load WinCon Server.
6. Open the *q_boot_upm_ZZ.wcp* WinCon project, where 'ZZ' corresponds to the type of data acquisition card being used – either Q4 or Q8.
7. Start WinCon by clicking on the green START button on the WinCon Server Window.
8. The *Left* and *Right* LEDs should stop flashing and the window shown in Figure 4 should be prompted. This implies the UPM amplifier is *ready* to be enabled.




Figure 4 Message prompt after running *q_boot_upm_ZZ*

9. Another (and not recommended!) way to stop the flashing of the LEDs is to push the *Reset* button located on the UPM front panel. This bypasses the need for the previously described UPM initialization procedure. However, this is not the recommended way of operation as it overrides the UPM safety watchdog put in place to detect whether the UPM system is properly connected to your computer.



10. **PRESS DOWN on the RED BUTTON of the deadman switch in case of emergency.** If something goes wrong during an experiment, pressing the red button of the deadman switch disables the amplifier and shuts off the the DC motor power.

Note that this initialization procedure does not enable the amplifier and therefore the motor cannot be driven yet. The amplifier is only enabled when running an actual supplied WinCon laboratory controller. The amplifier is disabled when the WinCon controller terminates. The digital signals required to initialize the UPM and the signals used to enable the amplifier are described in Appendix A.

2.3. Data Acquisition System

The system supplied may consist of either a Q4 or Q8 data acquisition card along with either a Q4 or Q8 extended terminal board card. Figure 5 depicts a Q8 Extended Terminal Card attached to a Q8 Data Acquisition Card (DAC) inside the computer. The DAC is equipped with eight analog input channels, eight analog output channels, and eight encoder channels. The analog outputs channels #0 and #4, all the analog input channels, and the encoder channels #0 and #4 are integrated in the *Table X* and *Table Y* connectors on the terminal board. The signals carried by the *Table X* and *Table Y* cables are listed in Section 3.4. The Q8 DAQ specifications are given in Table 3.






Figure 5 Q8 Extended Terminal Board

3. Connection Procedure

The different cables used to connect the various components of the shake table system is described in Section 3.1. The connections between the different terminal boards and the data acquisition cards are explained in Section 3.2. In Section 3.3, typical connections between the DAC, UPM, and shake table are described for a shake table in the x -axis configuration without any test structures mounted. In Section 3.4, the various signals carried by the serial cables between the UPM, the DAQ, and the shake table are described.

3.1. Cable Nomenclature

The cables used to connect DAC, UPM, and shake table are described below in Table 4.

Cable	Description
 <p data-bbox="269 1308 727 1346"><i>Figure 6 "Motor" Cable</i></p>	<p data-bbox="735 963 1375 1178">The "Motor" cable corresponds to the 3-phase motor power leads. This cable is designed to connect from the Quanser's Universal Power Module model 50-25-3PHI (i.e. the output of the power module after signal amplification) to the brushless DC motor of the shake table.</p>
 <p data-bbox="269 1719 727 1766"><i>Figure 7 "To Device" Cable</i></p>	<p data-bbox="735 1356 1375 1591">The "To Device" cable is a DB15 cable that connects the shake table circuit board to the UPM. It carries to the UPM the three limit sensors' signals and the motor encoder signals. It also supplies the DC power required by the different sensors.</p>





Cable	Description
 <p data-bbox="277 667 618 699"><i>Figure 8 "From MultiQ" Cable</i></p>	<p data-bbox="743 338 1377 653">The "From MultiQ" cable connects the UPM to the data acquisition card terminal board. It is compatible with Quanser's quick-connect system. It carries the motor encoder signals, limit sensor signals, calibrate signal, and the S1, S2, S3, and S4 analog signals from the UPM. From the DAC, the cable carries the control signal (to be amplified and sent to the motor) as well as the calibrate and enable digital signals</p>
 <p data-bbox="277 1087 651 1119"><i>Figure 9 "Emergency Stop" Cable</i></p>	<p data-bbox="743 758 1377 898">The "Emergency Stop" cable has a 6-pin-mini-DIN connector that connects to the side of the UPM. The UPM is enabled when the safety pushbutton switch is not pressed.</p>
 <p data-bbox="277 1377 570 1409"><i>Figure 10 "Encoder" Cable</i></p>	<p data-bbox="743 1163 1377 1409">The "Encoder" cable is a 5-pin-stereo-DIN-to-5-pin-stereo-DIN cable. It can directly connect an encoder to the data acquisition card terminal board. This cable carries the encoder signals and encoder DC power supply. Note that the signals from the built-in encoder on the motor of the shake table is carried by the "To Device" cable.</p>
 <p data-bbox="277 1713 711 1745"><i>Figure 11 "From Analog Sensors" Cable</i></p>	<p data-bbox="743 1478 1377 1717">The "From Analog Sensors" cable is a 6-pin-mini-DIN-to-6-pin-mini-DIN cable that can be used to connect any potential plant sensor to the UPM such as accelerometers. It can provide a $\pm 12\text{VDC}$ bias to analog sensors and carry their voltage signals to the DAC terminal board via the UPM.</p>

Table 4 Cable Nomenclature

3.2. Connecting the Terminal Board

This section assumes the data acquisition card is properly installed, as discussed in the *Q8 Manual*. Table 5 summarizes the connections between the Q4 and Q8 data acquisition cards (DACs) and the Q4 and Q8 extended terminal boards (ETBs).

Data Acquisition Card	Extended Terminal Board	Connections
Q8	Q8	J1 -> CHANNEL 1 J2 -> CHANNEL 2 J3 -> CHANNEL 3
Q4	Q4	J1 -> CHANNEL 1 J3 -> CHANNEL 3
Q8	Q4	J1 -> CHANNEL 1 J2 -> Not used J3 -> CHANNEL 3
Q4	Q8	J1 -> CHANNEL 1 Not used -> CHANNEL 2 J3 -> CHANNEL 3

Table 5 Connecting various DACs and ETBs

If the supplied data acquisition card is a Q8 DAC and the terminal board is also Q8 then the 'J1', 'J2', and 'J3' ribbon cables from the Q8 DAC should be connected to the inputs on the Q8 Extended Terminal Board labeled 'CABLE 1', 'CABLE 2', and 'CABLE 3', respectively. For a Q4 DAC and a Q4 ETB, connect the 'J1' cable from the DAC to the 'CABLE 1' input on the terminal board and the 'J3' cable to 'CABLE 3' on the terminal board.

The Q4 DAC is compatible with a Q8 Extended Terminal Board. In this configuration, the 'J1' and 'J3' cable from the Q4 DAC is connected to 'CABLE 1' and 'CABLE 3' on the Q8 ETB. The 'CABLE 2' connection on the ETB would not be used in this setup. Further, the Q8 DAC can be interfaced with the Q4 Extended Terminal Board. In this scenario, the 'J1' and 'J3' cable is connected to the 'CABLE 1' and 'CABLE 3' on the Q4 ETB. The 'J2' cable is not used and may be disconnected from the Q8 DAC.

3.3. Typical Connections

The connections described in Table 6 correspond to the labels in Figures 12, 13, and 14 .

Cable	From	To	Cable	Description
1	Table X on DAC	From MultiQ on UPM	25-pin serial	Input: Receives the accelerometer (S1), encoder, calibrate, and limit detector signals from UPM. Output: Drives amplifier on UPM and sends the calibrate and enable signals to the PIC on the UPM.
2	To Device on UPM	Circuit board on shake table	15-pin serial	Receives the encoder and limit detector signals from the shake table.
3	Motor on UPM	Motor on shake table	4-pin	Connects the shake table's motor leads to the amplifier on the UPM.
4	S1 on UPM	Accelerometer on shake table	6-pin mini DIN to 6-pin mini DIN	Connects the accelerometer attached to the shake table to the analog sensor input on the UPM.

Table 6 Typical Shake Table Connections




Figure 12 Q8 Extended Terminal Board




Figure 13 Front Panel of UPM




Figure 14 Shake Table Connections

3.4. Signals in 'Table X' Connection

As depicted in Figure 12, the Q8 Extended Terminal Board does not have separate analog input channels and does not have the Encoder #0 and Encoder #4 connectors. The A/D channels #0, #1, #2, and #3, and encoder channel #0 are integrated in the *Table X* connection and, similarly, the A/D channels #4, #5, #6, and #7, and encoder channel #4 are integrated in the *Table Y* connection. The limit detector signals – *Left*, *Home*, and *Right* – and the *calibrate* and *enable* signals from the PIC in the UPM are also carried in the *Table X* connection (when in the *x*-axis table configuration). Table 7 specifies the various signals carried between the UPM and *Table X* connection. The *Table X* connector on the Q4 Extended Terminal Board carries the same signals as the Q8 ETB *Table X* connection (i.e. Q4 ETB has no *Table Y* connector).

Signal	WinCon Interface	Description
D/A #0	Analog Output: Channel 0	Drives the amplifier in the UPM.
A/D #0	Analog Input: Channel 0	Analog sensor (i.e. accelerometer) sensor connected to <i>S1</i> on <i>x</i> -axis UPM.
A/D #1	Analog Input: Channel 1	Analog sensor (i.e. accelerometer) sensor connected to <i>S2</i> on <i>x</i> -axis UPM.
A/D #2	Analog Input: Channel 2	Analog sensor (i.e. accelerometer) sensor connected to <i>S3</i> on <i>x</i> -axis UPM.
A/D #3	Analog Input: Channel 3	Analog sensor (i.e. accelerometer) sensor connected to <i>S4</i> on <i>x</i> -axis UPM.
Encoder #0	Encoder Input: Channel 4	Measurement from encoder attached to the shake table motor.
DI #0	Digital Input: Channel 0	Left limit detector signal.
DI #1	Digital Input: Channel 1	Home limit detector signal.
DI #2	Digital Input: Channel 2	Right limit detector signal.
DI #3	Digital Input: Channel 3	Calibrate signal.
DO #0	Digital Output: Channel 8	Sends calibrate signal to PIC on UPM.
DO #1	Digital Output: Channel 9	Sends enable signal to PIC on UPM.

Table 7 *Table X* Connection Signals

The analog input channels #1, #2, and #3 are not required if the shake table is used only in the *x*-axis configuration with no test structures attached. However, consider the shake table setup with a two story building. In this configuration, there are three accelerometers

to be read – one mounted on the shake table, a second attached on first floor of the building, and a third fastened onto the second floor of the structure. The shake table, floor 1, and floor 2 accelerometers would be connected to the UPM analog inputs S1, S2, and S3. Since these signals are carried by the *Table X* connection, they can be interfaced in *WinCon* using the *Analog Input* block with channels #0, #1, and #2, respectively.

As mentioned, a second y-axis shake table can be coupled with an x-axis shake table. In this configuration, a second UPM is required for the y-axis table and the signals between this UPM and *Table Y* on the DAC is listed in Table 8.

Signal	WinCon Interface	Description
D/A #4	Analog Output: Channel 4	Drives the amplifier in the UPM.
A/D #4	Analog Input: Channel 4	Analog sensor (i.e. accelerometer) sensor connected to <i>S1</i> on y-axis UPM.
A/D #5	Analog Input: Channel 5	Analog sensor (i.e. accelerometer) sensor connected to <i>S2</i> on y-axis UPM.
A/D #6	Analog Input: Channel 6	Analog sensor (i.e. accelerometer) sensor connected to <i>S3</i> on y-axis UPM.
A/D #7	Analog Input: Channel 7	Analog sensor (i.e. accelerometer) sensor connected to <i>S4</i> on y-axis UPM.
Encoder #4	Encoder Input: Channel 4	Measurement from encoder attached to the shake table motor.
DI #4	Digital Input: Channel 4	Left limit detector signal.
DI #5	Digital Input: Channel 5	Home limit detector signal.
DI #6	Digital Input: Channel 6	Right limit detector signal.
DI #7	Digital Input: Channel 7	Calibrate signal.
DO #4	Digital Output: Channel 10	Sends calibrate signal to PIC on UPM.
DO #5	Digital Output: Channel 11	Sends enable signal to PIC on UPM.

Table 8 *Table Y* Connection Signals

4. Running Experiments with WinCon

WinCon is a software that runs Simulink models in realtime on a PC. The actual WinCon controller is built from a Simulink diagram designed by a user. Various Simulink models

and their corresponding WinCon controllers are supplied. Further, MATLAB script files used to load parameters used by the Simulink diagrams are given as well as a `q_scale.dll` file used to simulate real earthquakes on the shake table. Table 9 summarizes the various file extensions and describes the associated file.

File Extension	Description of File
*.mdl	Simulink model of the controller.
*.m	Matlab script file that sets gains and various other parameters in the Simulink diagram.
*.wcl	WinCon controller file generated from the Simulink model.
*.wcp	WinCon project file contains pre-defined plots and a control panel.

Table 9 File Extensions Description

4.1. Supplied Simulink Models, WinCon Projects and Software

The shake table system is supplied with the files listed in Table 10. The 'ZZ' suffix of some file names denotes the DAC card the file is compatible with and is either 'Q4', 'Q8', 'MQ3', or 'MQPCI'. The WinCon Project files were generated using the Simulink model of the same file name.

File Name	Description
Simulink Model	
<code>q_boot_upm_ZZ.mdl</code>	Initializes the UPM.
<code>q_cal_x_ZZ.mdl</code>	Calibrates the table to return to the home position.
<code>q_sine_x_ZZ.mdl</code>	Sends a sinusoidal with a specified amplitude and frequency to the shake table.
<code>q_sweep_x_ZZ.mdl</code>	Sends a sine sweep to the shake table for generating the frequency response.
<code>q_earthquake_x_ZZ.mdl</code>	General file that runs scaled historical earthquake data on the shake table.
<code>q_elcen_x_ZZ.mdl</code>	Exact copy of <code>q_earthquake_x_ZZ.mdl</code> but it is associated with the <code>q_elcen_x_ZZ.wcp</code> WinCon project.

File Name	Description
q_hach_x_ZZ.mdl	Exact copy of q_earthquake_x_ZZ.mdl but it is associated with the q_hach_x_ZZ.wcp WinCon project.
q_kobe_x_ZZ.mdl	Exact copy of q_earthquake_x_ZZ.mdl but it is associated with the q_kobe_x_ZZ.wcp WinCon project.
q_north_x_ZZ.mdl	Exact copy of q_earthquake_x_ZZ.mdl but it is associated with the q_north_x_ZZ.wcp WinCon project.
WinCon Project File	
q_boot_upm_ZZ.wcp	Run before performing any experiments to initialize the shake table. See Section 4.2.
q_cal_x_ZZ.wcp	Return table to the zero position. See Section 4.3.
q_sine_x_ZZ.wcp	Sends a use-specified sine wave to the shake table.
q_sweep_x_ZZ.wcp	Sends a sine sweep to the shake table for generating the frequency response. See Section 4.4.
q_north_x_ZZ.wcp	Runs Northridge Earthquake.
q_elcen_x_ZZ.wcp	Runs El Centro Earthquake.
q_hach_x_ZZ.wcp	Runs Hachimoto Earthquake.
q_kobe_x_ZZ.wcp	Runs Kobe Earthquake.
Matlab Script Files	
q_gain.m	Calculates feedback gains used by the shake table.
o_north.m	Historical data of the Northridge earthquake.
o_elcen.m	Historical data of the El Centro earthquake.
o_hach.m	Historical data of the Hachimoto earthquake.
o_kobe.m	Historical data of the Kobe earthquake.
Other	
q_scale.dll	File that scales down actual earthquake data to fit the shake table.

Table 10 Supplied Matlab, Simulink, and WinCon Files

4.2. Calibrating Table to 'Home'

The table should initially begin at the center or *Home* position before running any experiment. The table can be calibrated to the *Home* position using WinCon and the limit sensors installed on the shake table. Follow these steps to calibrate the table:

- Step 1. Ensure the UPM 50-25-PHI has been initialized as instructed in Section 2.2.4.
- Step 2. Load *WinCon*.
- Step 3. Open the project file 'q_cal_x_ZZ.wcp'.
- Step 4. Click on the *START* button in the *WinCon Server* window.
- Step 5. The UPM LEDs *Cal*, *OK*, and *Enable* LEDs should all be lit as the table slowly moves from its left or right position to the mid-stroke position. Depending on its starting position, the table may initially move towards the left or right limit, reverse directions, and then move towards the mid-stroke position. The table should stop moving when it is approximately in the center at which point the *Home* LED on the UPM will go ON and the message prompt shown in Figure 15 is displayed.



Figure 15 Message prompt after running q_cal_x_ZZ



- Step 6. **PRESS DOWN on the RED BUTTON of the deadman switch in case of emergency.** If something goes wrong during an experiment, pressing the red button of the deadman switch disables the amplifier and shuts off the DC motor power.
- Step 7. Alternatively, the knurled knob at the end of the table can be used to manually return the table to its home position. The *Home* LED on the UPM will be lit when this position is reached.
- Step 8. If the table is not moving consult the troubleshooting guide at the end of this reference manual.

Note that when the UPM is placed in the calibration mode, that is when the *Cal*, *OK*, and *Enable* LEDs are lit, the amplifier remains enabled when the *Left* or *Right* proximity sensor are triggered but is disabled when the *Home* limit sensor is activated. In contrast, the amplifier is disabled if the *Left* or *Right* sensor is triggered when the UPM is in the *enabled* state. The UPM is in the enabled state when the *OK* and *Enable* LEDs are lit and the UPM is placed in this state when running earthquakes and other laboratory files.

4.3. Sending Sine Wave to Shake Table

The shake table can be fed a sinusoidal signal of varying frequency and amplitude. Although there is not much analysis that can be made on the results, it is a good test to ensure the system is operating correctly. Follow this method to run the project:

Step 1. Ensure the amplifier has been initialized as discussed in Section 2.2.4.

Step 2. **Ensure table is at *HOME* position before running any experiment.**

Otherwise the experiment may stop prematurely because the table reached the left or right limit sensors. See the procedure in Section 4.2 for calibration procedure.

Step 3. Load *WinCon*.

Step 4. Open the project file '*q_sine_x_ZZ.wcp*'. As shown in Figure 16, the control panel has two knobs that enable the user to vary the amplitude and frequency of the sine wave.




Figure 16 *q_sine_x_ZZ* Control Panel

Step 5. Click on the *START* button in the *WinCon Server* window.

Step 6. The *Enable* and *OK* LEDs on the UPM should be lit. Consult the troubleshooting guide if this is not the case.

Step 7. The scope displays the commanded position and the resulting position of the table measured using its encoder. Figure 17 shows the scope when a sine wave with an amplitude of 0.5 in and a frequency of 5 Hz is given (by setting the control panel knobs as shown in Figure 16).




Figure 17 Shake Table Commanded and Measured Sine Position (in)



Step 8. **PRESS DOWN on the RED BUTTON of the deadman switch in case of emergency.** If something goes wrong during an experiment, pressing the red button of the deadman switch disables the amplifier and shuts off the DC motor power.

Step 9. Click on the *STOP* button in the *WinCon Server* window to terminate sine wave controller.

4.4. Variables Available for Plotting

In Figure 17, two variables were observed on the plot – 'Table Command Position (in)' and 'Table Position (in) <encoder>'. The variable label includes a name describing the data, its units, and the corresponding sensor indicated in the <...> brackets. For example, the 'Table Position (in) <encoder>' is the position of the shake table in inches attained using an encoder. The <...> is not included for input variables such as the reference position signal 'Table Command Position (in)'. Table 11 lists all the input and output variables available for plotting in the 'q_sine_x_ZZ.wcp', 'q_sweep_x_ZZ.wcp', 'q_north_x_ZZ.wcp', 'q_elcen_x_ZZ.wcp', 'q_hach_x_ZZ.wcp', and 'q_kobe_x_ZZ.wcp' projects. Note that some variables are given in both imperial and metric units.

Variable	Description
Input Variables	
Table Command Position (in)	Commanded position in inches.
Table Command Position (cm)	Commanded position in centimeters.
Desired Accel (g) <workspace>	Scaled acceleration from real earthquake data generated by <code>q_scale</code> and stored in Matlab workspace in units relative to the Earth's gravity.
Desired Accel (m/sec ²) <workspace>	Same as variable above except accelerations are stored in m/s^2 .
Current Command (A)	Current outputted to shake table from controller in amps.
Output Variables	
Table Position (in) <encoder>	Shake table position measured in inches using table encoder.
Table Position (cm) <encoder>	Same as above variable except units are in centimeters.
Table Speed (in/s) <encoder>	Shake table speed measured in inches per second using table encoder.
Table Speed (cm/s) <encoder>	Same as above variable except units are in centimeters.
Ball Screw Position (deg) <encoder>	Angle of ball screw measured in inches using table encoder.
Position Error (in) <encoder>	Control error in inches between reference position and actual position measured using the table encoder.
Position Error (cm) <encoder>	Same as above variable except units are in centimeters.
Table Accel (g) <accelerometer 0>	Acceleration of the shake table relative to Earth's gravity measured using accelerometer.
Table Accel (m/sec ²) <accelerometer 0>	Same as above variable except units are in m/s^2 .

Variable	Description
Table Accel (g) <encoder>	Acceleration of the shake table relative to Earth's gravity measured using encoder (double derivative).
Table Accel (m/sec2) <encoder>	Same as above variable except units are in m/s^2 .
Floor 1 Accel (g) <accelerometer 1>	Acceleration of structure's first floor relative to Earth's gravity measured using accelerometer fastened to that floor.
Floor 1 Accel (m/sec2) <accelerometer 1>	Same as above variable except units are in m/s^2 .
Floor 2 Accel (g) <accelerometer 2>	Acceleration of structure's second floor relative to Earth's gravity measured using accelerometer fastened to that floor.
Floor 2 Accel (m/sec2) <accelerometer 2>	Same as above variable except units are in m/s^2 .

Table 11 Variables Available for Plotting

Follow the procedure below to open plot a new variable, add variables to an existing plot, and adjust the time scale of the scope:

- Step 1. Open the list of available variables to be plotted by clicking on the *Open Plot* button in the *WinCon Server* window shown in Figure 18.




Figure 18 WinCon Server Window

- Step 2. Open the plots to be viewed in real-time by selecting the appropriate corresponding variables. For example, as depicted in Figure 19, to view the acceleration of the shake table measured from the accelerometer in g units select the variable Table Accel (g) <accelerometer 0>.




Figure 19 Variables Available for Plotting

- Step 3. Additional variables can be viewed on the same plot by selecting the *File* menu on the scope, clicking on *Variables*, and choosing the variables to be added. The *Select variables to display* window is similar to Figure 19 and can also be accessed by clicking right on the plot area.
- Step 4. The time scale of a plot can be adjusted by selecting *Update* on the scope and choosing *Time Buffer*, as shown in Figure 20.




Figure 20 Changing Time Buffer Size on Scope

4.5. Finding Frequency Response of a Structure Floor

The frequency response of a structure's floor can be found by applying a sine sweep from 1 Hz to 15 Hz in 30 s with a 0.2 cm amplitude to the table and measuring the resulting accelerations. Follow the procedure below to find the frequency response:

Step 1. Ensure the amplifier has been initialized as discussed in Section 2.2.4.

Step 2. **Ensure table is at HOME position before running any experiment.**

Otherwise the experiment may stop prematurely because the table reached the left or right limit sensors. See the procedure in Section 4.2 for calibration procedure.

Step 3. Load *WinCon*.

Step 4. Open the project file 'q_sweep_x_zz.wcp'. As shown in Figure 21, the control panel has a knob that allows the user to change how much the amplitude increments during the sweep.




Figure 21 Sine Sweep Control Panel

Step 5. Click on the *START* button in the *WinCon Server* window. By default the project opens with a scope showing the response of the table accelerometer.

Step 6. **PRESS DOWN on the RED BUTTON of the deadman switch in case of emergency.** If something goes wrong during an experiment, pressing the red button of the deadman switch disables the amplifier and shuts off the DC motor power.

Step 7. *WinCon* will restart the sine sweep after it is complete in 30 seconds. Click on the *STOP* button in the *WinCon Server* window to end the *WinCon* session.



The data read from the sensors can be saved in Matlab for analysis. For example, the supplied script 'freq1_15.m' uses FFT commands and the frequency response measured for floor structures to calculate the transfer function.

4.6. Performing Analysis on Collected Data

The data shown in a scope can be saved as a Matlab script file and used for analysis later. The scope is saved by choosing *Save As M-File* under the *Save* item in the *File* menu of the scope. The plot can be viewed by running the script in Matlab. The script also loads the time and data values of the plot, called `plot_time` and `plot_data`, into the workspace. This can be used for analysis or generating other plots.

When running the system in real-time the data in the scope is constantly being updated. The scope can be frozen by clicking on *Update* and selecting *Freeze Plot*. This halts the updating and makes it easier for the correct data to be captured. The scope can be unfrozen by selecting *Real-Time* under the *Update* menu on the scope.

4.7. Running a Standard Earthquake

Actual earthquake data can be scaled and ran on the shake table. There are four standard historical earthquakes that are already scaled for the user to test on the shake table. They are the Northridge, El Centro, Hachimoto, and Kobe earthquakes. Follow the procedure below to simulate one of these earthquakes on the shake table:

Step 1. Ensure the amplifier has been initialized as discussed in Section 2.2.4.

Step 2. **Ensure table is at HOME position before running any experiment.**

Otherwise the experiment may stop prematurely because the table reached the left or right limit sensors. See the procedure in Section 4.2 for calibration procedure.

Step 3. Load *WinCon*.

Step 4. Open the earthquake project file. For example, open '`q_north_x_ZZ.wcp`' to run the Northridge earthquake. The earthquakes' corresponding project file names are:

Northridge – `q_north_x_ZZ.wcp`

El Centro – `q_elcen_x_ZZ.wcp`

Hachimoto – `q_hach_x_ZZ.wcp`

Kobe – `q_kobe_x_ZZ.wcp`

Step 5. Click on the *START* button in the *WinCon Server* window.

Step 6. **PRESS DOWN on the RED BUTTON of the deadman switch in case of emergency.** If something goes wrong during an experiment, pressing the red button of the deadman switch disables the amplifier and shuts off the DC motor power.

Step 7. *WinCon* stops automatically after the earthquake data has run through. The duration of the session depends on the earthquake project selected.

The data read from the sensors can be saved in Matlab for analysis, as discussed in Section 4.7.



4.8. Scaling a Real Earthquake

New earthquake data can also be ran on the shake table. However, it must first be scaled down to fit the table. The actual earthquake data can be scaled using the function

$$[Tc, Xc, Ac, Te] = q_scale(t, a, xmax),$$

where:

Variable	Description	Units
<i>t</i>	Array of time at equal sampling intervals in seconds	s
<i>a</i>	Array of acceleration record that matches <i>t</i> array	g
<i>xmax</i>	Maximum deviation of motion from the home position	cm
<i>Tc</i>	Command time array	s
<i>Xc</i>	Position command array	cm
<i>Ac</i>	Acceleration array found by differentiating <i>Xc</i> twice.	cm·s ⁻¹
<i>Te</i>	Duration of run.	s

The user supplies the earthquake's time and position data along with the maximum deviation of the shake table.



Variable *xmax* should not exceed the limit of the shake table.

The function returns scaled time, position, acceleration, and duration of the earthquake. This returned array can then be used in a Simulink diagram to run the earthquake on the shake table.

For example, the new earthquake data *tnew* and *anew* is to be scaled down for use on the shake table. The *xmax* variable is set to 3 cm to remain in the safety limits of the table. The data is scaled using the following command in the Matlab prompt:

```
[Tc, Xc, Ac, Te] = q_scale(tnew, anew, 3.0).
```

Here is a sample output of the file:

```
Original sampling period:    0.02000
Scaling acceleration record
```

```
Step 1 of 3
Step 2 of 3
Step 3 of 3
Optimization ratio when done = 1.000000 Time = 9.908512
Warning: Subscript indices must be integer values.
*** Done ***
*** Displacement scaled from original movement of 27.46
cm to 3.00 cm
*** Time scaled from original duration of 29.98 seconds
to 9.91 seconds
*** Record size is 1550 samples

*** Use of this Software is under license from Quanser
Consulting Inc.
*** Any results derived from this use should be duly
acknowledged by the statement:
*** Acceleration and position scaling performed using
software licensed from Quanser Consulting Inc.
```

After scaling the earthquake data, `q_scale` generates the plot shown in Figure 22. The upper graph compares the real and scaled earthquake accelerations and the bottom graph depicts the position reference given to the shake table. Note that the accelerations overlap when plotted on the same time-scale because both the amplitude and the time is attenuated.




Figure 22 Real vs. Table Acceleration and Position Commanded to Shake Table

The arrays T_c , X_c , A_c , and T_e returned by the `q_scale` function can be used in a Simulink diagram to simulate earthquakes on the shake table. The actual acceleration measured from the shake table accelerometer should match the scaled accelerations from the `q_scale` function when the shake table's reference position is the X_c generated by the `q_scale` function. However, the measured accelerations from the table should be compared with the desired acceleration from the `q_scale` function in the frequency domain (i.e. spectral analysis). If their correlation is analyzed in the time domain there will be a time delay between the actual and desired accelerations.

4.9. Compiling a New Earthquake

This section describes how to create a new WinCon project to run new earthquake data on the shake table. Follow the method below:



- Step 1. Ensure the amplifier has been initialized as discussed in Section 2.2.4.
- Step 2. **Ensure table is at *HOME* position before running any experiment.** Otherwise the experiment may stop prematurely because the table reached the left or right limit sensors. See the procedure in Section 4.2 for calibration procedure.
- Step 3. Enter the time, t_{new} , and acceleration, a_{new} , of the actual earthquake in the Matlab workspace.
- Step 4. As described in Section 4.7, scale the data to fit the shake table using:
 $[T_c, X_c, A_c, T_e] = q_scale(t_{new}, a_{new}, x_{max})$. Ensure the return variables are exactly as specified.
- Step 5. Open the Simulink model called `q_earthquake_x_ZZ.mdl`. This is a standard Simulink file that uses the arrays T_c , X_c , and A_c , and the parameter T_e to simulate the earthquake on the shake table. The Simulink diagram therefore runs whatever earthquake is loaded in the Matlab workspace.
- Step 6. Save `q_earthquake_x_ZZ.mdl` as another Simulink file describing the earthquake. For example, `q_earthquake_california_x_ZZ.mdl`.
- Step 7. Run the Matlab script file `q_gain.m` to set all the parameters required for the earthquake Simulink model. This includes the ω_a and ω_f low-pass filter parameters, the ω_d high-pass filter parameter, and the control gains K_p , K_d , and K_f .



It is suggested the default filter parameters and control gains set by `q_gain.m` be used.

- Step 8. Click on *WinCon* in the Simulink diagram menu and select *Build*. As the code is being generated the Matlab window outputs a series of messages. This process may be lengthy on first usage due to the amount of files that need to be generated for real-time execution.
- Step 9. The code is finished being built when the *WinCon Server* window appears.

- Step 10. Open the plots to be viewed in real-time by clicking on *Open Plot* in the *WinCon Server Window* and selecting the appropriate corresponding variables. See Section 4.5 for instructions on how to select variables for plotting.
- Step 11. Adjust the time scale of the plot (s) to view the entire earthquake response by selecting *Update* on the scope and choosing *Time Buffer*. Set the buffer to a few seconds more than the duration of the earthquake (T_e value in Matlab workspace).
- Step 12. The current plot, real-time controller, and data loaded in the workspace can all be saved as a WinCon project for future use (similar to the standard earthquakes supplied). Go to *File* in the *WinCon Server* window and select *Save As* to save this package as a * .wcp file.
- Step 13. Click *START* on the *WinCon Server* window.
- Step 14. **PRESS DOWN on the RED BUTTON of the deadman switch in case of emergency.** If something goes wrong during an experiment, pressing the red button of the deadman switch disables the amplifier and shuts off the DC motor power.
- Step 15. WinCon stops automatically after the earthquake duration of the earthquake.
- Step 16. Collect the plot data by selecting *File* on the scope menu and choosing *Save As M-File* under the *Save* menu item, as explained in Section 4.7. The plot of a sensor can be viewed by running the saved script in Matlab.



5. Troubleshooting Guide

This section provides the user with a list of solutions to the questions that may occur when setting up the shake table.

- Q1. Why are the *Left* and *Right* LEDs on the UPM flashing?
The UPM has not been initialized yet. See Section 2.2.4 for the UPM 50-25-3PHI initialization procedure.
- Q2. Why is the *Left* or *Right* LED lit after undergoing the UPM initialization procedure?
The table was above the *Left* or *Right* proximity sensors when the boot-up procedure was ran. See Section 4.2 to calibrate the table to the *Home* position
- Q3. Why is the *OK* LED on the UPM not lit when running a WinCon project?
The E-Stop button is either pressed down or improperly connected to the UPM. Stop the WinCon controller and turn off the UPM. Then, verify that the deadman switch and the UPM are properly connected and ensure the E-stop button is in the released upright position.
- Q4. Why is the *Enable* LED on the UPM not lit when **running** a WinCon project?
This indicates that the UPM amplifier is not *ready* to be enabled. Go through the UPM initialization procedure detailed in Section 2.2.4 and the calibration procedure in Section 4.2.
- Q5. Why is the shake table not moving when running *q_cal_x_ZZ.wcp*, *q_sine_x_ZZ.wcp*, *q_sweep_x_ZZ.wcp*, *q_north_x_ZZ.wcp*, *q_elcen_x_ZZ.wcp*, *q_hach_x_ZZ.wcp*, or *q_kobe_x_ZZ.wcp* WinCon projects?
Is the red power LED in the top-left corner of the UPM lit? If not turn the switch to the OFF position and ensure the AC cord is securely connected. If after switching the UPM ON the LED is still not lit, the fuse may be blown. Replace the fuse and try re-powering the UPM.
Is the red LED on the terminal board lit? If NOT then the fuse may be blown, there may be a lack of power being supplied to the terminal board, or some other problem is associated with the board. See the corresponding data acquisition card manual for details on handling this situation.
See Section 2.2.4 and go through the UPM 50-25-3PHI initialization procedure. Once complete the red light power diode on the UPM should be ON. The *Left*, *Home*, or *Right* LED could be ON as well depending on the location of the table during the boot-up procedure.
Go through the calibration procedure detailed in Section 4.2. If the table does

not move towards the *Home* position and the **OK LED on the UPM is OFF** then the E-stop button may be pressed down. Stop the WinCon controller, shut off the UPM, and make sure the E-stop button is in the *upright* position (i.e. wind the knob clockwise indicated by the arrows) and confirm that it is properly connected to the UPM. Try again to calibrate the shake table as described in Section 4.2

If the table still does not move to the *Home* position then double-check all the connections, especially the connections from the UPM to the shake table and retry the calibration.

Appendix A

A.1. Signals used to Initialize 50-25-3PHI UPM

The *q_boot_upm_ZZ* WinCon controller generates and sends the enable and calibration signals shown in Figure 23 to the UPM's *AMP_EN* and *AMP_CAL* control lines, respectively. The enable and calibrate signals are both initialized at 0V in WinCon. The WinCon controller then brings the UPM's *AMP_CAL* line high, connected to Digital Output #8, and sends a low pulse for 200 milliseconds. It also pulls the *AMP_EN* line, connected to Digital Output #9, to low. WinCon automatically stops the real-time code after 0.5 seconds. This should stop the flashing and make the amplifier ready to be enabled. You can now exit WinCon without saving the project.




Figure 23 UPM Initialization Signals

A.2. Signals used to Enable 50-25-3PHI UPM

The UPM amplifier is enabled by any WinCon controller that sends a signal to the motor. The UPM is in the enable state when the *Enable* and *OK* LEDs are lit and the signals required to place it in this mode is shown in Figure 24.




Figure 24 UPM Amplifier Enable Signals

The 'q_sine_x_zz' WinCon controller generates and sends the enable and calibration signals shown in Figure 25 to the UPM's *AMP_CAL*, connected to Digital Output #8, and *AMP_EN*, connected to Digital Output #9, control lines. This is in addition to sending a user-controlled sine wave. The enable and calibrate signals are both initialized to 0V in WinCon. The WinCon controller keeps the UPM's *AMP_CAL* line to 0V for the duration of the session. The *AMP_EN* is initially set to 1V and after 0.5 seconds is pulsed down to 0V for 200 milliseconds. The UPM amplifier remains enabled as long as *AMP_CAL* sits at 0V while *AMP_EN* stays at 1V. The PIC in the UPM disables the amplifier when the WinCon controller is terminated (because it brings *AMP_CAL* and *AMP_EN* to 0V on exit) or if the *Left* or *Right* proximity sensors are activated.

Note that this series of signals is required to run any real-time experiments using the 50-25-3PHI UPM and the amplifier is only enabled after 0.7 seconds.

A.3. Signals used to Calibrate 50-25-3PHI UPM

The UPM must be placed into calibration mode in order to auto-center the table. The UPM is in calibration mode when its *Cal*, *Enable*, and *OK* LEDs are lit. In normal operation, the amplifier is disabled when the *Left* or *Right* proximity sensors are triggered. In this case, the amplifier is disabled when the *Home* sensor is activated. The enable and calibration signals needed to place the UPM in the calibration mode is explained next.




Figure 25 UPM Calibration Signals

The 'q_cal_x_zz.wcp' WinCon project generates and sends the enable and calibration signals shown in Figure 25 to the UPM's *AMP_CAL*, connected to Digital Output #8, and *AMP_EN*, connected to Digital Output #9, control lines. The enable and calibrate signals are both initialized at zero in WinCon. The WinCon controller brings the UPM's *AMP_CAL* line to high and then brings it to 0V after 1.1 seconds. The *AMP_EN* is initially set to 1V and after 1.2 seconds is pulsed down to 0V for 200 milliseconds. After this initial sequence, the amplifier in the UPM remains enabled as long as *AMP_CAL* sits at 0V while *AMP_EN* stays at 1V. The WinCon controller stops when the *Home* position has been reached and it sets the *AMP_CAL* and *AMP_EN* control lines back down to 0V before terminating, effectively disabling the amplifier.